


MTB - WARNING!

Ensure Clearance
Between Wheel &
Aeroclam.

**No Warranty Caused
by Contact Damage**



Movement

Slight side to side
movement at the rear
of the Aeroclam when
tightened is quite normal.

Especially so with the
thinner metal seat rails.
It's Designed to be like this.

DO NOT OVERTIGHTEN trying to
eliminate this movement.

